#### **DEFENSE LOGISTICS AGENCY**

**AMERICA'S COMBAT LOGISTICS SUPPORT AGENCY** 







# FARM TO FLEET INDUSTRY DAY

DLA Energy Quality & Technical Support

Mr. George C. Treloar 30 January 2014



### Introduction

- DLA Energy Quality Organization
- Pre-award Survey










## **Technical Quality & Standardization**





**Quality Assurance** 



Acquisition Support

Investigate / Resolve CDCs & PQDRs



Petroleum, Coal, Chemicals and Aerospace QA Policy

Quality Assurance QA

Off-spec
Product Disposition

Quality Assurance Training

Into-plane

QA

Policy


Measurement & Quantity Determination

Lab Contract Oversight





#### **Worldwide Locations**






## **Pre-award Survey**

- Technical -- Major Factor A
- Production -- Major Factor B
- Quality Assurance -- Major Factor C
- Transportation -- Other Factor B
- Security -- Other Factor D
- Plant Safety -- Other Factor E
- Other



### **Bulk Petroleum Supply Chain – Now & Future**





Property	MIL-DTL-5624 FT-SPK or HEFA-SPK	ASTM D7566 FT-SPK or HEFA-SPK	ASTM Test Method
Flash Point, ° C, min	60.0	38.0	D56, D93 <sup>1/2/</sup> , or D3828
Density at 15° C			D1298 or D4052 <sup>1/</sup>
kg/L, min	0.750	0.730	
kg/L, max	0.770	0.770	
Freezing Point, °C, max	-46	-40	D2386 <sup>1/</sup> , D5972, D7153, or D7154
Derived Cetane Number, min	40	N/A	D6890 <sup>1</sup> / or D7170

<sup>1/</sup> Referee Test Method.

ASTM D56 may give results up to 1° C below the ASTM D93 results.

<sup>2/</sup> ASTM D3828 may give results up to 1.7° C below the ASTM D93 results.



## **Contract Quality Assurance (CQA)**

• Inspect at Source / Accept at Source (SS)



• Inspect at Source / Accept at Destination (SD)



Inspect at Destination / Accept at Destination (DD)





## **Summary**

- DLA Energy Quality Organization
- Pre-ward Survey









# QUESTIONS?

#### **DEFENSE LOGISTICS AGENCY**

AMERICA'S COMBAT LOGISTICS SUPPORT AGENCY

